

2128 WOMEN'S NAUGATUCK SHIRT

SIZES XS-3XL

- :: 58% Cotton/42% Polyester yarn dye pique (5.01 oz/yd², 170GSM)
- :: Made to be worn whichever way you like -tucked or untucked



BACK VIEW



COMFORT & CONVENIENCE

- :: Eye-catching gingham trim at the inside neck and cuffs adds a subtle touch of style
- :: Drop tail hem in front and back with side vents allow for ease of movement
- :: Self-fabric collar with interfacing for stability
- :: Made to be worn whichever way you like -tucked or untucked

FABRIC

58% Cotton/42% Polyester yarn dye pique (5.01 oz/yd², 170GSM)

SIZES

Sizes XS-3XL

COLORS

010 Black (Solid), 377 Blue Chambray, 379 Denim Chambray, 380 Grey Chambray

GARMENT CARE

Machine wash cold with like colors. Gentle cycle. Only non-chlorine bleach when needed. Tumble dry low. Do not iron. Do not dry clean. Do not use softeners

DECORATION RECOMMENDATIONS

Embroidery: Ballpoint 70/10 needle. 2 Cutaway (no show mesh) stacked and rotated into a multipoint star. Topical Solvent recommended if small letters are included.

Heat Transfer: Max heat recommended is 315°F

Screen Printing: Automatic printing process is recommended. Maximum number of colors recommended is 4. Poly Low Bleed ink recommended for both white and dark ink colors. Catalyst recommended. Dryer temperature should not exceed 315°F.

010 BLACK
(SOLID)

377 BLUE
CHAMBRAY

379 DENIM
CHAMBRAY

380 GREY
CHAMBRAY

NAUGATUCK SHIRT WOMEN'S 2128	XS	S	M	L	XL	2XL	3XL	TOLERANCE
BODY LENGTH measure from neck (CB neck)	26 ½	27	27 ½	28 ¼	29	29½	30	½ +/-
ACROSS SHOULDER	14 ½	15	15 ½	16 ¼	17	17 ¾	18 ½	½ +/-
CHEST WIDTH measure 1 inch below armhole	18 ½	19 ½	20 ½	22	23 ½	25 ½	27 ½	½ +/-
BOTTOM OPENING WIDTH RELAXED 1/2	19	20	21	22 ½	24	26	28	½ +/-
SLEEVE LENGTH measure from CB	23 ¼	23 ¾	24 ½	25 ¼	26	26 ½	27	¼ +/-

KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED