

# 5006 WOMEN'S HYANNIS PORT ANORAK

SIZES XXS-3XL

:: Outer shell is 100% nylon rip stop, lining is 55% cotton/45% polyester woven lining (1.47 oz/yd2)

:: Quarter zip pullover anorak styling

:: Hood features shockcord drawstring

3-piece hood features shockcord drawstring

Quarter Zip styling

Zippered pouch pocket

Elasticized cuffs

Droptail hem

BACK VIEW



**COMFORT & CONVENIENCE**

- :: Quarter zip pullover anorak styling
- :: Hood features shockcord drawstring
- :: Front pouch pocket and zipper pocket
- :: Features drop tail hem and elastic cuffs

**FABRIC**

Outer shell is 100% nylon rip stop, lining is 55% cotton/45% polyester woven lining (1.47 oz/yd2)

**SIZES**

Sizes XXS-3XL

**COLORS**

Navy/White Gingham 740

**GARMENT CARE**

Machine wash lukewarm, Mild detergent, Gentle cycle, Hang dry, Do not tumble or machine dry

**DECORATION RECOMMENDATIONS**

Embroidery: Ballpoint 75/10 needle. Tearway backing. Topical solvent not necessary.

Heat Transfer: Max heat recommended is 305°F

Screen Printing: Automatic printing process is recommended. Maximum number of colors recommended is 1. IC Nylon ink recommended for both white and dark ink colors. Catalyst not necessary. Dryer temperature should not exceed 290°F.

740  
NAVY/WHITE  
GINGHAM



HYANNIS PORT ANORAK WOMEN'S 5006	XXS	XS	S	M	L	XL	2XL	3XL	TOLERANCE
<b>BODY LENGTH</b> measure from neck (CB neck)	28	28½	29	29½	30¼	31	31½	32	½ +/-
<b>SHOULDER TO SHOULDER</b>	19½	20	20½	21	21¾	22½	23¼	24	¼ +/-
<b>CHEST WIDTH</b> measure 1 inch below armhole	20	21	22	23	24½	26	28	30	½ +/-
<b>BOTTOM OPENING WIDTH RELAXED 1/2</b>	20	21	22	23	24½	26	28	30	½ +/-
<b>SLEEVE LENGTH</b> measure from CB	32¼	32¾	33¾	34	34¾	35½	36	36½	¾ +/-

KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED